



AREA OF FOCUS

MASTERPLAN SCOPE BOX

Mayfield Village
Parkview Pool Pergola Area Study

02.01.2019




PROVIDE PORTABLE PROPANE GRILLS IN POOL AREA FOR RENTAL PARTIES.

MOVE FENCE TO OUTSIDE COLUMNS TO INCLUDE EXISTING PAVING INTO THE POOL SNACK BAR AREA

PROVIDE (1-2) NEW UMBRELLAS

REMOVE EXISTING PAVING AND PROVIDE NEW TURF



ALTERNATE 1:
NEW PICNIC TABLES SHELTER
WITH BBQ GRILLS AT EACH




ALTERNATE 2:
NEW PICNIC TABLES WITH BBQ
GRILLS AT EACH

*PURPLE AREAS INDICATE
POTENTIAL LOCATIONS FOR
TABLES ONLY AND GRILLS, NO
NEED FOR SHADE STRUCTURE
WITH THE EXISTING TREES

Mayfield Village
Parkview Pool Pergola Area Study

02.01.2019







NOTE:
SHADE SAILS AND STRUCTURE IS TO BE
BID AS DESIGN / BUILD WITH AN
ALLOWANCE TO BE PROVIDED BY THE
CONTRACTOR. SHADE SAIL CONSULTANT
TO SUBMIT THEIR DESIGN FOR THE
VILLAGES APPROVAL ONCE THE
CONTRACTOR IS AWARDED THE
CONTRACT.



MAINTENANCE ITEMS:
1. EXISTING PERGOLA NEEDS
REPAIRED/ RESTAINED
2. TILE DETAIL CRACKING
THROUGHOUT
3. CAST STONE CAPS NEED CLEANED/
REPAIRED/REPLACED

EXISTING COLUMN:
TOP OF COLUMN 9'-8"



COLUMN REPAIR: CUT TILE
DETAIL OFF TOP OF COLUMN
DROP COLUMN TO EXISTING
BOTTOM OF TILE DETAIL +/- 8'-0"

Mayfield Village
Parkview Pool Pergola Area Study



02.01.2019